AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General	4	issues	L/ IVI/ FI	
Environment				
Floor surface	V			
Signs	V			
Gates	V			
Fences	V			
Benches	V			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	V			
Multi Play	V			
Roundabout	V			
Spring See-Saw	V			
2Bay Swing	V			

Date	.23/02/2023Time Complete	e d 143	0		
Weather (Conditions - Dull				
Additional Observations					
Signature	B Nanson	Name			
Signature		Name			

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	V			
Pavilion Inc fire extinguishers	~			
Defibrillator – solid icons displayed	~			
Sewerage Plant (Listen and warning light)	V			
Container	~			
Outfield	~			
Site Boundaries, Fences and Hedges	~			
Bins	~			

Weather	Conditions	Dull

Additional Observations

Signature	B Nanson	Name	
Signature		Name	
Date23/02	/2023		