

AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 01

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date13/01/2020..... **Time Completed** ...1145.....








Weather Conditions: Overcast, very wet underfoot

Additional Observations

Signature Name ...Doreen Matthews.....

Signature NameBryan Nanson.....

AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 01

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances				
Pavilion Inc fire extinguishers				
Sewerage Plant (Listen and warning light)				
Container				
Outfield				
Site Boundaries, Fences and Hedges				
Bins				

Weather Conditions Overcast, very wet underfoot

Additional Observations

Signature Name Doreen Matthews

Signature Name Bryan Nanson

Date13/01/2020.....