AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	V			
Environment				
Floor surface				
Signs	V			
Gates	V			
Fences	V			
Benches	V			
	21/2		Risk	Time Scale
Equipment	OK?	Issues	L/M/H	
Turnstile				
Multi Play	V			
Roundabout	V			
Spring See-Saw	V			
2Bay Swing	V			

Date	07/04/2025	Time Complete	d 0930			
Weather Conditions Sunny, blues skies, cool						
Additional Observations						
Signatu	reB Nanson	Name				
Signatu	re	Name				

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	V			
Pavilion Inc fire extinguishers	V			
Defibrillator – solid icons displayed	•			
CCTV Cameras - free from cobwebs	V			
Sewerage Plant (Listen and warning light)	~			
Container	V			
Outfield	•			
Site Boundaries, Fences and Hedges	•			
Bins	~			

Weather Conditions	Sunny, I	blues	skies,	cool
--------------------	----------	-------	--------	------

Additional Observations

Signature	B Nanson	Name	
J			
C:		Name	
Signature		Name	
Date 07	7/04/2025		