AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 42

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment	*			
Floor surface	*			
Signs				
Gates				
Fences	•			
Benches	•			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	~			
Multi Play	~			
Roundabout	~			
Spring See-Saw	~			
2Bay Swing	~			

Date	27 December 2020		Time C	ompleted11.00am
Weathe	r Conditions	Dry and cloudy		
Additio	nal Observations			
Signatu	re		Name	Doreen Matthews
Signatur	·e		Name	

1

^{*}Inspection number to be added by Inspector

AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 42

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	~			
Pavilion Inc fire extinguishers	~			
Sewerage Plant (Listen and warning light)	~			
Container	~			
Outfield	~			
Site Boundaries, Fences and Hedges	~			
Bins	~			

Weather Conditions - Dry and cloudy

Additional (Observations
--------------	--------------

Signatur	re		Name	Doreen Matthews
Signatur	re		Name	
Date	27 Dece	ember 2020		

2

^{*}Inspection number to be added by Inspector