AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	V			
Environment	-			
Floor surface	~			
Signs	V			
Gates	V			
Fences	V			
Benches	V			
			Risk	Time Scale
Equipment	OK?	lssues	L/M/H	
Turnstile	~			
Multi Play	¥			
Roundabout	V			
Spring See-Saw	v			
2Bay Swing	✓			

Date08/05/2023/2023...... Time Completed1130......

Weather Conditions - Dull, light rain.

Additional Observations

Signature	B Nanson	Name	
Signature		Name	

(Version 1.1 Issued 07/11/2021)

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	~			
Pavilion Inc fire extinguishers	~			
Defibrillator – solid icons displayed	~			
Sewerage Plant (Listen and warning light)	~			
Container	~			
Outfield	~			
Site Boundaries, Fences and Hedges	~			
Bins	~	Both bins @ W Horse entrance full Bin @ A3090 ½ full		

Weather Conditions Dull, light rain

Additional Observations

Signature	B Nanson	Name	
Signature		Name	

Date ...08/05/2023.....

(Version 1.1 Issued 07/11/2021)