AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	V			
Environment				
Floor surface	V			
Signs	V			
Gates	V			
Fences	V			
Benches	V			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Equipment	4	133463	L/141/11	
Turnstile				
Multi Play	V			
iviuiti Fiay				
Roundabout				
	~			
Spring See-Saw				
2Bay Swing	~			

Date 04/09/2	023	Time Complet	ed143	0		
Weather Conditions - warm & sunny						
Additional Observations						
Signature	D M	latthews	Name			
Signature			Name			

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	•			
Pavilion Inc fire extinguishers	~			
Defibrillator – solid icons displayed	~			
Sewerage Plant (Listen and warning light)	•			
Container	•			
Outfield	•			
Site Boundaries, Fences and Hedges	•			
Bins	V	Recycle bin overflowing TVBC to be notified of failure to empty		

Weather	Conditions	warm	&	sunny	/
---------	------------	------	---	-------	---

Additional Observations

Signature	D Matthews	Name	
Signature		Name	
Date 04/09	/2023		