AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General				
Environment	•			
Floor surface	\checkmark			
Signs	\checkmark			
Gates	\checkmark			
Fences	\checkmark			
Benches	\checkmark			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	 Image: A start of the start of			
Multi Play	~			
Roundabout	~			
Spring See-Saw	~			
2Bay Swing	~			

Date 05/04/2021..... Time Completed ...15.30pm.....

Weather Conditions: Fair

Additional Observations

Signature	Name
Signature	Name

(Version 1.0 Issued 20/12/2020)

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	ОК	Issues	Risk	Time Scale
	?		L/M/H	
Entrances				
Pavilion Inc fire extinguishers				
Sewerage Plant (Listen and warning light)	\checkmark			
Container				
Outfield	\checkmark	Golfing holes far end of field Dog poo at corner of cricket pitch	L	
Site Boundaries, Fences and Hedges				
Bins		Car park ¼ full White Horse ½ full		

Weather Conditions: Fair

Additional Observations

Signature	NameDavid Stevens
Signature	Name

Date

(Version 1.0 Issued 20/12/2020)