AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	✓			
Environment	•			
Floor surface	✓			
Signs	√			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	√			
Multi Play	√			
Roundabout	√			
Spring See-Saw	√			
2Bay Swing	√			

Date	24 th April 2022	Time Completed	11:10am
------	-----------------------------	----------------	---------

Weather Conditions Sunny, dry, warm

Additional Observations

Signature CJ Ling Name CJ Ling

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	√			
Pavilion Inc fire extinguishers	√			
Defibrillator – solid icons displayed	✓			
Sewerage Plant (Listen and warning light)	√			
Container	√			
Outfield	✓			
Site Boundaries, Fences and Hedges	√			
Bins	√			

Weather	Conditions

Sunny, dry, warm

Additional Observations

Signature CJ Ling Name CJ Ling

Date 24th April 2022