AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	√			
Roundabout	√			
Spring See-Saw	√			
2Bay Swing	√			

Date 20 th March 2025 Time Completed 11:00	Date	11:00an
---	------	---------

Weather Conditions Dry, Overcast

Additional Observations

Signature CJ Ling Name CJ Ling

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	√			
Pavilion Inc fire extinguishers	√			
Defibrillator – solid icons displayed	√			
Sewerage Plant (Listen and warning light)	√			
Container	√			
Outfield	√			
Site Boundaries, Fences and Hedges	√			
Bins	√			

Additional Observations								
Signature	C J Ling	Name CJLing						

Dry, Overcast

Date 20th March 2025

Weather Conditions