

AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 41

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	OK			
Floor surface	OK			
Signs	Ok			
Gates	OK			
Fences	OK			
Benches	OK			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	OK			
Multi Play	OK			
Roundabout	OK			
Spring See-Saw	OK			
2Bay Swing	OK			

Date ...20/12/2020..... **Time Completed** ...15:00.....

Weather Conditions dry, sun

Additional Observations Ground wet underfoot

Signature Name Graham Roads

.....

Signature Name

AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 41

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	OK			
Pavilion Inc fire extinguishers	OK			
Sewerage Plant (Listen and warning light)	OK			
Container	OK			
Outfield	OK			
Site Boundaries, Fences and Hedges	OK			
Bins		Required emptying		

Weather Conditions dry, some sun,

Additional Observations

Outfield wet underfoot

A member of ANBCC was painting/repairing the scorers hut.

Signature Name ...Graham Roads.....

Signature Name

Date : 20/12/2020