

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

| Auxiliary Items | OK? | Issues | Risk L/M/H | Time Scale |
|---------------------|-----|--------|------------|------------|
| General Environment | OK | | | |
| Floor surface | OK | | | |
| Signs | OK | | | |
| Gates | OK | | | |
| Fences | OK | | | |
| Benches | OK | | | |
| Equipment | OK? | Issues | Risk L/M/H | Time Scale |
| Turnstile | OK | | | |
| Multi Play | OK | | | |
| Roundabout | OK | | | |
| Spring See-Saw | OK | | | |
| 2Bay Swing | OK | | | |

Date03/08/21..... **Time Completed** 17:15 pm.....

Weather Conditions dry cloud

Additional Observations The cricketers were preparing for the final of the Taurus Border League (?). ANBCC were not playing but the ground had been selected to host the final. A fine accolade for the club and our facilities!

Signature Name ...G Roads.....

Signature Name

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

| Area | OK ? | Issues | Risk L/M/H | Time Scale |
|---|---------|-----------------|---------------|------------|
| Entrances | OK | | | |
| Pavilion Inc fire extinguishers | OK | | | |
| Sewerage Plant (Listen and warning light) | OK | Noise, no light | | |
| Container | OK | | | |
| Outfield | OK | | | |
| Site Boundaries, Fences and Hedges | OK | | | |
| Bins | | Totally full | | |

Weather Conditions

Dry, cloud

Additional Observations

Signature Name ...G Roads.....

Signature Name

Date 03/08/21.....