## AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 31

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	<b>√</b>			
Environment	•			
Floor surface	<b>√</b>			
Signs	<b>√</b>			
Gates	<b>√</b>			
Fences	<b>√</b>			
Benches	<b>√</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	<b>√</b>			
Multi Play	<b>√</b>			
Roundabout	<b>√</b>			
Spring See-Saw	<b>√</b>			
2Bay Swing	<b>√</b>			

Date	15/09/2020	Time Completed 12:00
------	------------	----------------------

Weather Conditions Bright and sunny

**Additional Observations** 

Signature C J Ling Name C J LING

## AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 31

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	<b>V</b>			
Pavilion Inc fire extinguishers	<b>✓</b>			
Sewerage Plant (Listen and warning light)	<b>√</b>			
Container	<b>√</b>			
Outfield	<b>√</b>			
Site Boundaries, Fences and Hedges	<b>√</b>			
Bins	<b>√</b>			

W	eat	her	Con	diti	ons
vv	cat		CUII	ulu	UIIO

**Bright and sunny** 

**Additional Observations** 

Signature CJLing Name CJLING

Date 15/09/2020