## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment	$\checkmark$			
Floor surface	<b>~</b>	Broken glass beer bottle in corner nearest bins	Н	Immediate (already resolved)
Signs	$\checkmark$			
Gates	$\checkmark$			
Fences	$\checkmark$			
Benches	$\checkmark$			
Equipment	OK?	lssues	Risk L/M/H	Time Scale
Turnstile	<ul> <li>✓</li> </ul>			
Multi Play	$\checkmark$			
Roundabout	$\checkmark$			
Spring See-Saw	$\checkmark$			
2Bay Swing	$\checkmark$			

Date 28<sup>th</sup> March 2024 Time Completed 14:15am

Weather Conditions Rain, overcast, wet underfoot

**Additional Observations** 

Signature CJLing Name CJLing

(Version 1.1 Issued 07/11/2021)

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	$\checkmark$			
Pavilion Inc fire extinguishers	$\checkmark$			
Defibrillator – solid icons displayed	$\checkmark$			
Sewerage Plant (Listen and warning light)	<b>√</b>			
Container	$\checkmark$			
Outfield	$\checkmark$			
Site Boundaries, Fences and Hedges	$\checkmark$			
Bins	$\checkmark$			

Weather Conditions Rain, overcast, wet underfoot

Additional Observations

Signature CJLing Name CJLing

Date 28th March 2024

(Version 1.1 Issued 07/11/2021)